

Date: Thursday, 7/19/2007 2:22:50 PM  
 User: Kim Johnston

## Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: AFT TUBE ASSEMBLY
Job Number	: 33643		
Estimate Number	: 10699		
P.O. Number	: <u>N/A</u>	Part Number	: D3391025
This Issue	: 7/19/2007	S.O. No.	: <u>N/A</u>
Prsht Rev.	: NC	Drawing Number	: D3391 REV F
First Issue	: <u>N/A</u>	Project Number	: N/A
Previous Run	: 33642	Drawing Revision	: F
		Material	: <u>N/A</u>
		Due Date	: 7/30/2007
Written By	: <u>[Signature]</u>	Qty:	1 Um: Each
Checked & Approved By	: <u>[Signature]</u>		
Comment	Est Rev B 06-02-07 ECN773 dwg rev. D EC Est Rev: C 06-03-28 Update Manufacturing Instructions JLM est rev D 07.03.20 revF dwg ec		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D6014090	ALUMINUM EXTRUSION
-----	----------	--------------------



Comment: Qty.: 1.0000 f(s)/Unit Total : 1.0000 f(s)

ALUMINUM EXTRUSION

Pick:

Qty Part Number Description Batch

1 D6014-090 Extrusion 76546

Identify as D3391-3

BF 07.07.31

2.0	MORI SEIKI	MORI SEIKI CNC LATHE LARGE
-----	------------	----------------------------



Comment: MORI SEIKI CNC LATHE LARGE

Turn as per Folio FA599

Rev: AA & Dwg D3391 Rev: FBF 07-08-01

①

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	----------------------------------------



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

BF 07-08-01

①

4.0	HAAS1	HAAS CNC VERTICAL MACHINING #1
-----	-------	--------------------------------



Comment: HAAS

1-Machine as per Folio FA 599 Rev: AA & Dwg D3391 Rev: F

2-Deburr

BF 07-08-09

①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:22:50 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 33643

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

IF 07-08-09 (4)

6.0

QC8

SECOND CHECK



Comment: SECOND CHECK

J.L 07/08/10

7.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Drill ( PILOT HOLE) aft cap holes per Dwg D3391 using DT8803

DP 7-8-13

8.0

BENDING

BENDING MACHINE



Comment: NC Bender

Form as per Dwg D3391 Using Bend Prog 3391025

DP 7-8-13

9.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

En 07/08/14 (X1)

10.0

LANDING GEAR 1

LANDING GEAR RESOURCE 1



Comment: LANDING GEAR RESOURCE 1

1-Open Aft cap pilot hole to .208" as per Dwg D3391

2-Drill float bag holes using DT8809 as per Dwg D3391(Holes marked "A" Only.

3-Drill wearplate holes as per Dwg D3391 using DT8878(Mid Tube) & DT8217 Wearplate Jig .

\*\*\*\*\*Do Not Open To Finished Size\*\*\*\*\*

4-Drill Wearshoe holes as per DWG D3391 using DT8939 locating from 2 previously drilled aft wearplate holes.

5-Open up all wearshoe & wearplate and float bag holes to .257" + countersink as per Dwg D3391.

6-Deburr

DP 7-8-14  
DP 7-8-15

Tools: rill

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:22:50 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 33643

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

11.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

EP 07/08/15 (41)

12.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Acid etch and Alodine as per QSI 005 4.1

M-L

07/08/16

(1X)

13.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

M 105068

BR/M-L 07-08-16

(1)

14.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

FR 07/08/16 (1)

15.0

D2646

Aft Cap



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Aft Cap

Pick:

Qty

Part Number

Description Batch

1

D2646

Aft Cap

D31335

M-L

16.0

D35371

WEARPAD



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

WEARPAD

D33660 M-L

17.0

D35377

Wearpad



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Wearpad

D31911 M-L

18.0

D35531

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

Gasket

D31400

M-L 07/08/16

(1X)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:22:50 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 33643

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

19.0

D35533

Gasket



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)  
Gasket

*532745*

*m. h*

20.0

AESS10KB366

INSERT



Comment: Qty.: 14.0000 Each(s)/Unit Total : 14.0000 Each(s)  
Insert

Pick:

Qty Part Number Description Batch  
14 AESS10KB366 Insert

*m 10492*

*m. h / FL*

21.0

AESS10KB316

INSERT



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)  
INSERT

Pick:

Qty Part Number Description Batch  
2 AESS10KB316 Insert  
or NAS1330C3KB316

*m 17905*

*m. h / FL*

22.0

AESS10KB266

INSERT



Comment: Qty.: 6.0000 Each(s)/Unit Total : 6.0000 Each(s)  
INSERT

Pick:

Qty Part Number Description Batch  
2 AESS10KB266 Insert  
or NAS1330C3KB266

*m 17905*

*m. h / FL*

23.0

NAS1330C3KB166

INSERT



Comment: Qty.: 12.0000 Each(s)/Unit Total : 12.0000 Each(s)  
INSERT

Pick:

Qty Part Number Description Batch  
8 NAS1330C3KB166 Insert

*m 103279*

*m. h / FL* 07/08/18  
07/08/16 ①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries



Date: Thursday, 7/19/2007 2:22:50 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 33643

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

24.0

AN3C4A

BOLT



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Bolt

Pick:

Qty	Part Number	Description	Batch
2	AN3C4A	Bolt	m105057

ed/m-l

25.0

AN3C5A

Bolt



Comment: Qty.: 8.0000 Each(s)/Unit Total : 8.0000 Each(s)

Bolt

m104885

ed/m-l

26.0

AN960C10L

washer



Comment: Qty.: 10.0000 Each(s)/Unit Total : 10.0000 Each(s)

Inventory

Pick:

Qty	Part Number	Description	Batch
2	AN960C10L	Washer	m105143

ed/m-l

27.0

NAS1515H3L

WASHER



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

WASHER

Pick:

Qty	Part Number	Description	Batch
2	NAS1515H3L	Washer	m104603

ed/m-l

28.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: SMALL & MEDIUM FAB RESOURCE 1

1-Install inserts as per Dwg D3391

2-Install Aft Cap as per Dwg D3391

A/R Sikaflex-241/-291

Sikaflex expiry date:

m104989  
08-01

07-08-17

29.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/08/17

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: 15 Date: 07/09/20  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 7/19/2007 2:22:50 PM  
User: Kim Johnston

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: AFT TUBE ASSEMBLY

Job Number: 33643

Part Number: D3391025

Job Number:



Seq. #:

Machine Or Operation:

Description :

30.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: \_\_\_\_\_

33522A

31.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

①  
DAR108/22

Job Completion



U A-08-22

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

DART AEROSPACE LTD		Work Order:	33643
Description: Float Skidtube (412)		Part Number:	D3391-3
Inspection Dwg: D3391 Rev: F		Page 1 of 1	


### FIRST ARTICLE INSPECTION CHECKLIST

☒ First Article ☐ Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
14.000	+/-0.010	14.000	✓			
3.500	+/-0.010	3.495	✓			
88.93	+/-0.030	88.93	✓			
44.995	+/-0.030	44.995	✓			
3.200	+/-0.010	3.203	✓			
1.526	+0.000/-0.030	1.520	✓			
0.200	+/-0.010	0.197	✓			
7.500	+/-0.010	7.500	✓			
27.750	+/-0.010	27.750	✓			
31.750	+/-0.010	31.750	✓			
35.250	+/-0.010	35.250	✓			
0.400	+/-0.010	.				L.G.
3.300	+/-0.010	3.302	✓			
0.200	+/-0.010	0.197	✓			
3.520	+/-0.010	3.522	✓			
0.687	+0.010/-0.000	0.694	✓			
R0.062	+/-0.010	0.062	✓			
Ø0.484	+0.005/-0.001	0.448	✓			

Measured by: <u>BEI</u>	Audited by: <u>J.L</u>	Prototype Approval:	N/A
Date: <u>07-08-09</u>	Date: <u>07/08/10</u>	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	06.04.24	New Issue P/O D3391-025	KJ/JLM	
B	06.06.19	Dwg revision update	KJ/JLM	
C	07.04.20	Ø0.208 dimension removed	KJ/JLM	



#### D3391-041/-043 FLOAT SKIDTUBE ASSEMBLY PARTS LIST

QTY	QTY	PART NUMBER	DESCRIPTION
X	X	D3391-041	FLOAT SKIDTUBE ASSEMBLY
		D3391-043	FLOAT SKIDTUBE ASSEMBLY
1		D3391-011	FWD TUBE ASSEMBLY
1		D3391-013	MID TUBE ASSEMBLY
1		D3391-015	AFT TUBE ASSEMBLY
	1	D3391-021	FWD TUBE ASSEMBLY
	1	D3391-023	MID TUBE ASSEMBLY
	1	D3391-025	AFT TUBE ASSEMBLY
1	1	D3564-1	WEARSHOE
1	1	D3564-3	WEARSHOE
1	1	D3564-5	WEARSHOE
2	2	D3566-1	GASKET
1	1	D3566-5	GASKET
24	24	AN3C4A	BOLT
12	12	AN3C6A	BOLT
8	8	AN3C7A	BOLT
44	44	AN960C10L	WASHER
4	4	MS27039C4-12	SCREW
4	4	NAS1515H4L	WASHER
4	4	AN960C416L	WASHER

#### GENERAL NOTES

- ALL DIMENSIONS ARE IN INCHES
- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- FINISH: ACID ETCH AND ALODINE PER DART QSI 005 4.1  
POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3
- SPRAY INSIDE OF TUBE WITH A COAT OF LPS LABORATORIES "LPS-3" AFTER FINISH AND AFTER INSTALLATION OF INSERTS. COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEK DEGREASER.
- USE DART DRILL TEMPLATE DT8217 TO LOCATE AND DRILL 'E' SIZE HOLES (#0.250-#0.257) FOR WEARSHOE INSERTS. C'SINK #0.391/#0.425 x 100" AS APPLICABLE AND INSTALL INSERTS EXCEPT WHERE INDICATED.

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

F	07.01.18	ADD SS WEARSHOE, GASKET REMOVE FWD SADDLE HOLE -011/-021
E	06.04.25	CHANGE TOLERANCE, EASE MANUFACTURE
D	06.01.23	UPDATE TOLERANCE, CHANGE HOLE SIZE
C	05.09.27	LENGTHEN AFT EXTENSION
B	05.06.10	DRAWING UPDATES
A	05.02.07	NEW ISSUE
DESIGN	DRAWN BY	
CHECKED	APPROVED	
DATE	TITLE	
07.01.18	412 FLOAT SKIDTUBE	

**DART** DART AEROSPACE USA, INC.  
PORT HADLOCK, WA

DRAWING NO.  
D3391

REV. F


SHEET 1 OF 5

SCALE


NTS

WORK ORDER  
NO. 35643  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
ENGINEERING  
RETURN TO  
SHOP COPY



**RELEASED**  
 07.03.13 PH  
 per ECN #934




**D3391-011 ASSEMBLY AND BENDING DETAIL**




**D3391-021 ASSEMBLY AND BENDING DETAIL**



**SECTION D-D (SCALE 1:5)**



**SECTION C-C (SCALE 1:5)**



**VIEW Z-Z (SCALE 1:5)**


**D3391-011/-021 FWD TUBE ASSEMBLY PARTS LIST**

QTY - 011	QTY - 021	PART NUMBER	DESCRIPTION
X	X	D3391-011	FWD TUBE ASSEMBLY
		D3391-021	FWD TUBE ASSEMBLY
1	1	D6013-047	FWD TUBE
1	1	D3401-041	TOW CAP
1	1	D3564-13	WEARSHOE
1	1	D3566-13	GASKET
10	10	AN3C4A	BOLT
4	4	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER
30	20	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)


5  
 DRILL "E"  
 (Ø0.250-Ø0.257)  
 C'SINK (Ø0.391 X 100'')  
 INSTALL  
 NAS1330S3KB166  
 (12 PLACES)

STOP COPY  
 RETURN TO  
 ENGINEERING  
 UNCONTROLLED COPY  
 SUBJECT TO AMENDMENT  
 WITHOUT NOTICE

WORK ORDER  
 33643






**SECTION B-B (SCALE 1:5)**




**D3391-1 DRILLING AND CUTTING DETAIL  
 (MAKE FROM D6013-047 SKIDTUBE MATERIAL)**

COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.		DESIGN PH	DRAWN BY PH	DART AEROSPACE USA, INC. PORT HADLOCK, OH	
CHECKED [Signature]	APPROVED [Signature]	DRAWING NO. D3391		REV. F SHEET 2 OF 5	
DATE 07.01.18		TITLE 412 FLOAT SKIDTUBE		SCALE 1:10	




**D3391-023 ASSEMBLY DETAIL**




**D3391-013/-023 MID TUBE ASSEMBLY PARTS LIST**

QTY - 013	QTY - 023	PART NUMBER	DESCRIPTION
X	X	D3391-013	MID TUBE ASSEMBLY
		D3391-023	MID TUBE ASSEMBLY
1	1	D2500-1-100	EXTRUSION
1	1	D3389-1	WEB
24	20	NAS1330S3KB116	INSERT (OR NAS1330C3KB116)
24	10	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4		NAS1329S4KB140	INSERT (OR NAS1329C3KB140)
4		NAS1515H3L	WASHER
4		AN960C10L	WASHER
4		NAS1515H4L	WASHER
4		AN960C416L	WASHER
4		MS27039C1-09	SCREW
4		MS27039C4-08	SCREW


**SECTION L-L**  
(SCALE 1:4)




**SECTION M-M**  
(SCALE 1:4)





**SECTION N-N**  
(SCALE 1:4)




**SECTION O-O**  
(SCALE 1:4)




**SECTION P-P**  
(SCALE 1:4)




**SECTION X-X**  
(SCALE 1:2)



**SECTION Y-Y**  
(SCALE 1:4)



**SECTION G-G**  
(SCALE 1:4)




**SECTION H-H**  
(SCALE 1:4)

- D3391-013/-023 MID TUBE ASSEMBLY**
- MATERIAL: MAKE FROM D2500-1-100 EXTRUSION
  - INSTALL D3389-1 WEB TO OUTER TUBE USING SIKAFLEX-241/-291 PER OSI 015


WORK ORDER  
UNCONTROLLED COPY  
ENGINEERING  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.		DESIGN RH	DRAWN BY AH	<b>DART</b> DART AEROSPACE USA, INC. PORT HADLOCK, WA	REV. F
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.		CHECKED H	APPROVED H		DRAWING NO. D3391
		DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE		SCALE 1:20







**VIEW BB-BB**  
(SCALE 1:3)




**D3391-3 AFT DRILLING AND CUTTING DETAIL**  
(MAKE FROM D6014-090 SKIDTUBE MATERIAL)




**DETAIL V**  
(SCALE 1:2)




**SECTION AA-AA**  
(SCALE 1:2)




**SECTION N-N**  
(SCALE 1:2)



**SECTION P-P**  
(SCALE 1:2)




**SECTION Q-Q**  
(SCALE 1:2)




**SECTION R-R**  
(SCALE 1:2)

NO. 33642  
WORK ORDER  
SUBJECT TO AVIATION  
UNCONTROLLED COPY  
ENGINEERING  
RETURN TO  
SHOP COPY  
WITHOUT NOTICE



**DETAIL S**  
(SCALE 1:3)




**VIEW W-W**  
(SCALE 1:3)

**RELEASED**  
07.03.13 PH  
per ECN #934


COPYRIGHT © 2006 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.


DESIGN PH	DRAWN BY PH	<b>DART</b> DART AEROSPACE USA, INC. PORT HADLOCK, WA	REV. F
CHECKED H	APPROVED H	DRAWING NO. D3391	SHEET 4 OF 5
DATE 07.01.18	TITLE 412 FLOAT SKIDTUBE	SCALE 1:12	




D3391-015 BENDING AND ASSEMBLY DETAIL



D3391-025 BENDING AND ASSEMBLY DETAIL




D3391-015 INSERT AND WEARPAD INSTALLATION DETAIL (SEE TABLE)




D3391-025 INSERT AND WEARPAD INSTALLATION DETAIL (SEE TABLE)

D3391-015/-025 AFT TUBE ASSEMBLY PARTS LIST

QTY - 015	QTY - 025	PART NUMBER	DESCRIPTION
X	X	D3391-015	AFT TUBE ASSEMBLY
		D3391-025	AFT TUBE ASSEMBLY
1	1	D6014-090	AFT TUBE
1	1	D2846	AFT CAP
1	1	D3537-1	WEARPAD
1	1	D3537-7	WEARPAD
1	1	D3553-1	GASKET
1	1	D3553-3	GASKET
18	14	NAS1330S3KB366	INSERT (OR AES10KB366)
4	2	NAS1330S3KB316	INSERT (OR NAS1330C3KB316)
8	6	NAS1330S3KB266	INSERT (OR NAS1330C3KB266)
4	*	NAS1330S3KB216	INSERT (OR NAS1330C3KB216)
16	12	NAS1330S3KB166	INSERT (OR NAS1330C3KB166)
4		NAS1330S4KB151	INSERT (OR NAS1330C4KB151)
6	6	AN3C4A	BOLT
4	4	AN3C5A	BOLT
2	2	NAS1515H3L	WASHER
10	10	AN960C10L	WASHER




DRILL 'Q' (Ø0.332-Ø0.338)  
C'SINK (Ø0.529X100")  
NAS1330S4KB151 INSERT (1)  
(4 PLACES)



C'SINK AND INSTALL NAS1330S3KBXXX IN HOLES MARKED CS1-CS6 AS FOLLOWS

HOLES MARKED	QTY D3391-015	QTY D3391-025	C'SINK	P/N
CS1	18	14	Ø0.425	NAS1330S3KB366
CS2	4		Ø0.391	NAS1330S3KB366
CS3	4	2	Ø0.391	NAS1330S3KB316
CS4	8	6	Ø0.391	NAS1330S3KB266
CS5	4		Ø0.391	NAS1330S3KB216
CS6	16	12	Ø0.391	NAS1330S3KB166



RELEASED  
07.03.13 RH  
per ECU #934

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.		DESIGN PH	DRAWN BY RL	DART AEROSPACE USA, INC. PORT HADLOCK, WA	
CHECKED H	APPROVED H	DRAWING NO. D3391		REV. F SHEET 5 OF 5	
DATE 07.01.18		TITLE 412 FLOAT SKIDTUBE		SCALE 1:12	